



Toyota Motor Sales, U.S.A., Inc.
6565 Headquarters Drive
Plano, TX 75024

**URGENT EQUIPMENT SAFETY
RECALL**

The inspection and/or remedy
will be performed
FREE OF CHARGE to you.

IMPORTANT EQUIPMENT SAFETY RECALL (Remedy Notice)

**Defective Seatbelt Retractor Force Limiter
NHTSA Recall No. 22E-095**

Dear <Dealer Name>:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. Toyota has decided that a defect, which relates to motor vehicle safety, exists in certain Front Seatbelt Assemblies sold as service parts. You received this notice because our records indicate that your dealership may have purchased these service parts.

What is the condition?

A component in the subject front seat belt assemblies may not have been manufactured properly and may cause the seat belt to not operate as designed. **This can increase the risk of an injury in the event of certain types of crashes.**

Involved Part Numbers

Part Number	Affected Lot #	Description
73210-24171-A0		Belt Assy, Outside, RH (or LH)
73210-48130-A0		Belt Assy, Outside, RH (or LH)
73210-48130-B0	2E**/	Belt Assy, Outside, RH (or LH)
73220-24131-A0	2F**/	Belt Assy, Outside, RH (or LH)
73220-24131-C0	2G**/	Belt Assy, Outside, RH (or LH)
73220-33331-C1	2H**/	Belt Assy, Outside, RH (or LH)
73220-42221-B0	2I**	Belt Assy, Outside, RH (or LH)
73220-47051-B0		Belt Assy, Outside, RH (or LH)
73220-48040-A0		Belt Assy, Outside, RH (or LH)
73220-48052-A0		Belt Assy, Outside, RH (or LH)
73220-48110-A0		Belt Assy, Outside, RH (or LH)
73220-48110-B0		Belt Assy, Outside, RH (or LH)

Spanish translation on back side
Traducción en español en el lado inverso

What will Toyota do?

Toyota dealers are requested to review their inventory according to the procedure below. In addition, Toyota dealers are requested to contact their regional Field Technical Specialist who will provide additional direction on contacting potential purchasers of these service parts.


This is an important Safety Recall.

The remedy will take approximately 1.5 hours. However, depending on your work schedule, it may be necessary to make the vehicle available for a longer period of time. Please communicate the expected remedy time to the purchaser of the service parts.

- If the seat belt sold to a vehicle owner is for the front passenger seat, please advise the purchaser of the service part to avoid using the passenger seat location until the inspection/remedy can be performed.

Inspection Procedure

1. CONFIRM PART NUMBER IS IN PARTS LIST
2. IDENTIFY THE LOT NUMBER (4 digits) ON THE LABEL ON THE OUTSIDE OF THE BOX



3. DETERMINE IF THE LOT # IS FROM THE AFFECTED LOT BY CHECKING THE FIRST TWO DIGITS OF THE LOT NUMBER AND COMPARING TO THE AFFECTED LOT # IN THE TABLE ABOVE.

< Lot No. of NG parts > Lot No. consists of 4 digits

2E** / 2F** / 2G** / 2H** / 2I**

— Please go to Step 2

(Until 2D & from 2J are OK parts)

ex.) 2 = Year (1:2021, 2:2022)

E = Month (A: Jan., H: Aug., I: Sept., —)

** = Any number or alphabet

- a. IF LOT # **IS NOT** FROM THE AFFECTED LOT, NO FURTHER ACTION IS NEEDED
 - b. IF LOT # **IS** FROM THE AFFECTED LOT, PROCEED TO STEP 4
4. TAKE A PHOTO OF THE BOX LABEL WITH LOT NUMBER (4 digits) AND EMAIL PHOTO TO quality_compliance@toyota.com

If you believe that the dealer or Toyota has failed or is unable to remedy the defect within a reasonable time or without charge, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E., Washington, D.C. 20590, or call the toll free Vehicle Safety Hot Line at **1-888-327-4236 (TTY: 1-800-424-9153)**, or go to <http://www.safercar.gov>.

We have sent this notice in the interest of your continued satisfaction with our products. We sincerely regret any inconvenience this condition may have caused you.

Thank you for driving a Toyota.

Sincerely,

Toyota Motor Sales, USA